

1/64	=	.0156		33/64	=	.5156
1/32	=	.0312		17/32	=	.5312
3/64	=	.0469		35/64	=	.5469
1/16	=	.0625		9/16	=	.5625
5/64	=	.0781		37/64	=	.5781
3/32	=	.0937		19/32	=	.5937
7/64	=	.1093		39/64	=	.6094
1/8	=	.1250		5/8	=	.6250
9/64	=	.1406		41/64	=	.6406
5/32	=	.1562		21/32	=	.6562
11/64	=	.1719		43/64	=	.6719
3/16	=	.1875		11/16	=	.6875
13/64	=	.2031		45/64	=	.7031
7/32	=	.2187		23/32	=	.7187
15/64	=	.2344		47/64	=	.7344
1/4	=	.2500		3/4	=	.7500
17/64	=	.2656		49/64	=	.7656
9/32	=	.2812		25/32	=	.7812
19/64	=	.2969		51/64	=	.7969
5/16	=	.3125		13/16	=	.8125
21/64	=	.3281		53/64	=	.8281
11/32	=	.3437		27/32	=	.8437
23/64	=	.3594		55/64	=	.8594
3/8	=	.3750		7/8	=	.8750
25/64	=	.3906		57/64	=	.8906
13/32	=	.4062		29/32	=	.9062
27/64	=	.4219		59/64	=	.9219
7/16	=	.4375		15/16	=	.9375
29/64	=	.4531		61/64	=	.9531
15/32	=	.4687		31/32	=	.9687
31/64	=	.4844		63/64	=	.9844
1/2	=	.5000		1	=	1.0000